


Matagorda Island Restoration



Project Site



Western Marsh Site Conditions



Western Marsh Site Conditions




•Northern Culverts at B-SR-1



•Southern Culverts at B-SR-1

Western Marsh Site Conditions

•FH-SR-3 area. 3 Breaches



Western Marsh Site Conditions

- Breach east of new culvert



- Damage to unimproved culvert

